
Verifast **

Pneumatic Connection Diagram for VeriFast™ LVDT/IA Weld Bodies with RETRACTABLE PINS





CenterLine (Windsor) Limited

Tel: 519-734-8464, Email: info@cntrline.com, www.cntrline.com




Pneumatic Connection Diagram for VeriFast™ LVDT/IA Weld Bodies with NON-RETRACTABLE PINS



For your specific configuration, consult the VeriFast™ LVDT or VeriFast™ IA User Manual, available at www.cntrline.com

This information does not apply to:

- VeriFast™ LVDT/IA Clamp Mount Weld Bodies
- Ring weld or clinching applications



Patent: www.cntrline.com/patent



CenterLine (Windsor) Limited

Tel: 519-734-8464, Email: info@cntrline.com, www.cntrline.com

FDP-VFA-LVD-OI-QS-PR-1.1-1221